Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

 1307
 RESIDENCE
 NY Spills
 \$107488401

 NE
 2338 EAST 18TH ST
 N/A

> 1 1.667 mi. 8801 ft. BROOKLYN, NY

 Relative:
 SPILLS:

 Higher
 Name:
 RESIDENCE

 Actual:
 Address:
 2338 EAST 18TH ST

 18 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 0509741 / 2006-01-27

 Facility ID:
 0509741

 Facility Type:
 ER

 DER Facility ID:
 305593

 Site ID:
 355559

 DEC Region:
 2

Spill Cause: Housekeeping Spill Class: Not reported SWIS: 2401 Spill Date: 2005-11-14 Investigator: **SFRAHMAN** Referred To: Not reported Reported to Dept: 2005-11-14 CID: 407

Water Affected: Not reported Spill Source: Private Dwelling Spill Notifier: Local Agency Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust**: False Remediation Phase: 0 Date Entered In Computer: 2005-11-14

Date Entered In Computer: 2005-11-14
Spill Record Last Update: 2006-01-27
Spiller Name: UNKNOWN
Spiller Company: RESIDENCE
Spiller Address: 2338 EAST 18TH ST

Spiller Company: 001
Contact Name: UNKNOWN

DEC Memo:

Remarks:

"11.16.05 Sharif-Referred to En Con police for site inspection."

"caller states that homeowner does work on cars in the back of his house in a garage and doesn't propertly dispose any wastes."

All Materials:

 Site ID:
 355559

 Operable Unit ID:
 1112914

 Operable Unit:
 01

 Material ID:
 2102957

 Material Code:
 0021

Material Name: transmission fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported

Units: G Recovered: .00

Oxygenate: Not reported

 Site ID:
 355559

 Operable Unit ID:
 1112914

Map ID MAP FINDINGS
Direction

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

 Operable Unit:
 01

 Material ID:
 2102958

 Material Code:
 0064A

Material Name: unknown material Case No.: Not reported Material FA: Other Quantity: Not reported

Units: G Recovered: .00

Oxygenate: Not reported